



TEST COACH
CORPORATION

Firmware Change for Ultra FINN

Effective January 1, 2009 the firmware for the Ultra FINN has been updated to reflect the following changes:

1. Improved stability in the near infrared range for non-diffused, point source LEDs.
2. Improved differentiation between blue and deep green (wide-band, 520 nm) LEDs. A slight reduction in frequency of blue LEDs may be noticed with the new firmware.

All Ultra FINNs sold on or after January 1, 2009 have the new firmware at Rev A6. The A6 Rev level is labeled directly on the black molding of the Ultra FINN. The new part number is TCUF09SL.

Please note that the old part number will no longer be available.